Northway Corp
Subcontract to Ogden
Well Drlg.
Casing record

Pump test data 70 gpm
SWL 12'
PWL 85'
Yield

Acidized? Yes
Pump depth 140'
40' of 12" cemented
80 vs 36 grout
↓
estimated

Quantitative analysis on the sediment

Sediment analysis
Return sample to Bill Cook
for further analysis.

Cloudy water occurs during
initial pumping. After
level falls to 50'
water clears up.