STATE OF IOWA
DEPARTMENT OF ENVIRONMENTAL QUALITY


Place VAIL, IOWA Date Feb 20, 1973

Report on NEW WELL #4

By JERRY RATTENBORG Approved Director

Date of report Feb 22, 1973

THE following is supplied on the NEW WELL #4 at VAIL. THE PUMP has NOT been set - well is temporarily capped with a welded steel plate.



NOTES: 1) CONST. BY LAYNE-WESTERN

2) REPORTED LOW IRON, 20 gr. HARD

3) DO NOT KNOW if there is CASING below SCREEN, but would doubt it

4) BELIEVED to be grouted - evidence of neat cement on grind of casing.