

### Well Details

#### Help

Permit Number: 40612  
 Well Number: 2172183  
 County: \* LYON  
 Well Status: \* Active Logged  
 Geosam Reviewed:

### Other Well Users

There are currently no other well users.

### Previous Owners

There is currently no owner history.

### Current Property Owner Information

Name (F/M/L): \*  
 Company: \*  
 Street: \*  
 City: \* State: \* Iowa Zip: \*  
 Phone: ( ) -

### Well Location

If you intend to input 'GPS Readings', Please click on 'Populate PLS' button after you complete entering valid Lat/Long values.

Map Type: \*    
 Latitude \* Longitude: \*  
 PLS:  
 Section : 30 Township : 98 Range : 45 RangeDir : W  
 Qtr Sec 3: NW Qtr Sec 2: SE Qtr Sec 1: SW  
 Parcel Number:  
 E911 House Number: E911 Street: E911 City:

### Well Details

Date Completed: \* / /  
 Date Completed Confidence: \*  
 Known Questionable Guess

Samples have been submitted to IGS for analysis:

### \* Well Use

- Household
- Livestock
- Subdivision
- Commercial

# w#80936

Well Depth: \*

Well Depth Confidence: \*

Known    Questionable    Guess

Depth to Water:

Topography:    -- Select Topography --

Elevation:

Construction Method: \*    Auger, Bored or Bucket

Data Entered By:    Ivanmaanen

Well Driller: \*    VANDEBRAKE, LARRY - 5578

Contract Company:    Alton Well & Concrete Co., Inc. - Alton

Irrigation

Recreational

Dewatering

Injection

Test (water only)

Monitoring

Heat Pump

Descriptor: \*

Number of Wells: \*

## Well Developed

Well Was: \*    Pumped

For: \*    hours

At: \*    GPM

## Pump Installed

Yes    No

Explain:

## \*Well Formation Log

From	To	Lithology	Color	Comments
		soil or fill	Black	
		soil or fill	Black	
		sand	Yellow	
		sand	Yellow	
		sand and gravel	Yellow	
		sand and gravel	Yellow	
		sand and gravel	Yellow	
		sand and gravel	Yellow	
		sandy clay	Yellow	
		sandy clay	Yellow	

Remarks: (Including depth of drilling, fluids, materials, or tools, etc.)

0 characters entered. | 250 characters remaining.

## Well Construction Log

**\*Hole Size**

Top	Bottom	Hole Size	Comments

**\*Casing**

Casing Type	Top	Bottom	Diameter	ID/OD	STD/Thickness	Comments
PVC				-- ID/OD --		
PVC				-- ID/OD --		
PVC				-- ID/OD --		
PVC				-- ID/OD --		

**\*Grout**

Grouting Type	Grouting Method	Top	Bottom	Amount	Comments
Bentonite	Tremie			Bags	
Bentonite	Tremie			Bags	

**Well Screen**

Material	Diameter	Slot Size	Top	Bottom	Comments
Plastic					
Plastic					

**Bottom Capped**

Yes No

**Capping Material: \***

**Gravel Pack**

Top	Bottom	Gravel Type	Weight	Comments
		Pea gravel		
		Pea gravel		

**Seals and Packers**

**Seals Type/Depth** -- Seals Type -- / ft

Packers Type/Depth --Packers Type -- / ft

Well Water Information

Aquifer: \* Sand/Gravel

Main Water Supply Zone: \* From ft To ft

Static Water Level: \* ft Above Below GL Electric line

Pumping Water Level: \* ft below GL Electric line

A Yield of: \* GPM Volumetric

Measurements Taken at: 14 30 / /

Renovations

There are currently no results.

Water Tests

There are currently no results.

Plug Information

There are currently no results.

