

IOWA DNR Water Quality Bureau

Iowa's Private Well Tracking System

Department of Natural Resources

[EPD Index](#) | [Wastewater](#) | [Water Resources](#) | [Water Supply](#) | [Contact](#)

General

Reports

Members Area

Well Details

Help

Permit Number: 31447
 Well Number: 2144852
 County: * DELAWARE
 Well Status: * Active
 Geosam Reviewed:

Other Well Users

There are currently no other well users.

Previous Owners

There is currently no owner history.

Current Property Owner Information

Name (F/M/L): *
 Company: *
 Street: *
 City: * State: * Iowa Zip: *
 Phone: () -

Well Location

If you intend to input 'GPS Readings', Please click on 'Populate PLS' button after you complete entering valid Lat/Long values.

Map Type: *
 Latitude * Longitude *
 PLS:
 Section : 25 Township : 88 Range : 5 RangeDir : W
 Qtr Sec 3: NW Qtr Sec 2: NE Qtr Sec 1: NW
 Parcel Number:
 E911 House Number: E911 Street: E911 City:

Well Details

Date Completed: * / /
 Date Completed Confidence: *
 Known Questionable Guess
 Samples have been submitted to IGS for analysis:

* Well Use

Household
 Livestock
 Subdivision
 Commercial

Well Depth: *
Well Depth Confidence: *
 Known Questionable Guess
Depth to Water:
Topography: Level Surface
Elevation:
Construction Method: * Rotary Drill
Data Entered By: dlyons on Jan 19 2010 4:05PM
Well Driller: * OGDEN, BEN - 6714
Contract Company: Oasis Well Drilling - Manchester

Irrigation
 Recreational
 Dewatering
 Injection
 Test (water only)
 Monitoring
 Heat Pump

Descriptor: *
Number of Wells: *

Well Developed

Well Was: * Airlifted
For: * hours
At: * GPM

Pump Installed

Yes No

Explain:

***Well Formation Log**

From	To	Lithology	Color	Comments
		sand	Brown	
		limestone	Gray/Orangish	
		limestone	Gray	
		limestone	Tan	
		limestone	Gray	
		shale	No Color Noted	

Remarks: (Including depth of drilling, fluids, materials, or tools, etc.)

0 characters entered. | 250 characters remaining.

Well Construction Log

***Hole Size**

Top	Bottom	Hole Size	Comments

***Casing**

Casing Type	Top	Bottom	Diameter	ID/OD	STD/Thickness	Comments
PVC				OD		

***Grout**

Grouting Type	Grouting Method	Top	Bottom	Amount	Comments
One Step Bentonite Slur	Tremie			Bags	

Well Screen

Material	Diameter	Slot Size	Top	Bottom	Comments
-- Screen Material --					

Bottom Capped

Yes No

Capping Material: *

Gravel Pack

Top	Bottom	Gravel Type	Weight	Comments
		-- Gravel Type --		

Seals and Packers

Seals Type/Depth -- Seals Type -- / ft

Packers Type/Depth --Packers Type -- / ft

Well Water Information

Aquifer: * Limestone

Main Water Supply Zone: * From ft To ft

Static Water Level: * ft Above Below GL Estimate

Pumping Water Level: * ft below GL Estimate

A Yield of: * GPM Estimate

Measurements Taken at: 16 0 / /

Renovations

There are currently no results.

Water Tests

	Date Sampled	Date Entry	Coliform Tested	Coliform Present	Fecal Tested	Fecal Present	Nitrate Tested
View	08/17/2010	09/02/2010	Yes	No	Yes	No	Yes
View	09/12/2011	09/16/2011	Yes	No	Yes	No	Yes
View	06/05/2013	06/11/2013	Yes	Yes	Yes	No	Yes
View	06/25/2013	06/28/2013	Yes	No	Yes	No	Yes

Plug Information

There are currently no results.



State of Iowa | Dept. of Natural Resources | Environmental Protection Division | [Site Map/Search](#) | [Questions/Comments Email](#)

Common Downloads: [Microsoft Internet Explorer](#) | [Netscape Navigator/Communicator](#) | [Adobe Acrobat Reader](#) | [Other Downloads](#)

© 2000 State of Iowa EPD, All Rights Reserved.

Version: 2.0.1.3750

You are currently logged in as [benjamin-dellos@uiowa.edu](#) (View Only)