6404

Northway Well and Pump Co.

4895 8th Avenue
Marion, Iowa 52302
319-377-6339
1-800-747-6339

100 North 6th Street
Waukee, Iowa 50263
515-987-4575
1-800-747-4575

WELL TEST DATA REPORT

Customer Water Works Department City Strawberry Point
Location West of Maintenance Shop Well No. 5
Size Casing 8" T & C Total Depth 190 Construction Steel
Make Pump Grundfos Model No. SP45 No. of Stages 6
Diameter 6" Total Setting 168 Air Line Length Electronic Tape
Meter Used 4" Propeller Static Level 118.4

DATE	TIME	GPM	P.L.	D.D.	S.C.	P.S.I.	TEMP DISCHARGE DESCRIPTION
7-5-2017	8:30am	220	121.4	3	73.3	12	Cloudy
	8:35	200	124.9	6.5	30.76	8	Clear
	8:40	200	125.7	7.3	27.39	8	Clear
	8:45	200	125.7	7.3	27.39	8	Clear
	8:50	200	125.7	7.3	27.39	8	Clear
	9:00	200	125.7	7.3	27.39	8	Clear
	9:30	200	125.8	7.4	27.02	8	Clear
	10:00	200	125.8	7.4	27.02	8	Clear
	10:30	200	125.8	7.4	27.02	8	Clear
	11:00	200	125.9	7.5	26.66	8	Clear
	11:30	200	125.9	7.5	26.66	8	Clear
	12:00pm	200	125.9	7.5	26.66	8	Clear
	12:30	200	126.0	7.6	26.31	8	Clear
	1:00	200	126.1	7.7	25.9	8	Clear
	1:30	200	126.1	7.7	25.9	8	Clear
	2:00	200	126.2	7.8	25.64	8	Clear
	2:30	200	126.2	7.8	25.64	8	Clear
	3:00	200	126.2	7.8	25.64	8	Clear
	3:30	200	126.2	7.8	25.64	8	Clear
	4:00	200	126.3	7.9	25.31	8	Clear
	4:30	200	126.3	7.9	25.31	8	Clear
	5:00	200	126.3	7.9	25.31	8	Clear
	5:30	200	126.3	7.9	25.31	8	Clear
	PUMP OFF RECOVERY						
	5:35	119.2					
	5:40	118.4					

Note: The well was pumped for 4 hours on August 1, 2017 before water samples were collected.